

Linn Grove Dam

[Dams by River Index \(LHDrivers.html\)](#)[Next Dam Downstream \(LHDsiouxdam.html\)](#)

River/Stream: Little Sioux River

Location: Linn Grove, Buena Vista County

Latitude: 42.895592

Longitude: -95.244898

[Click here to view an aerial map of the dam.](#)

([http://maps.google.com/maps?](http://maps.google.com/maps?q=42.895592,-95.244898+%28Linn+Grove+Dam%29&z=15&ll=42.895592-95.244898&t=h)

[q=42.895592,-95.244898+%28Linn+Grove+Dam%29&z=15&ll=42.895592-95.244898&t=h](http://maps.google.com/maps?q=42.895592,-95.244898+%28Linn+Grove+Dam%29&z=15&ll=42.895592-95.244898&t=h))

Built: 1875

Owner: Buena Vista County Conservation Board

Height: 10 feet

Length: 210 feet

Hazards ([HazardDefs.html](#)): usage, height



([images/linngrovedam.jpg](#))



(./images/LinnGrove2.jpg)

Photo by Lynn Graesing

Fatalities 3

- June 29, 2013, Robert Wiese, lost control of a motor boat while launching it in high water above the dam
- May 30, 2000, Charles Ebel, fell in while fishing
- April 24, 1962, John Rex, fishing boat capsized
- June 26, 2010, close call for 3 swimmers
YouTube (http://www.youtube.com/watch?v=yJI-L_TKgoE)

Promoting river safety, education, and recreation

Last Updated: 8/2/2017